

Splice Damage Detection—Example

Complete Conveyor
Solutions...

Also available at all Fenner
Dunlop Branches:

For nearest branch:

www.fennerdunlop.com.au
Call: 1 800 FENNER

West Footscray, Revesby,
Kwinana, Brisbane, Cairns,
Emerald, Gladstone, Mackay,
Townsville, Rockhampton, Mt
Isa, Adelaide, Whyalla, Darwin,
Hunter (Somersby), Tasmania
(Camdale), Port Hedland,
Karratha, Wollongong, Victoria
(Dandenong South), New
Zealand (Oamaru).




FENNER DIAGNOSTICS

68—70 Chivers Road
Somersby NSW 2250
Australia

Phone: +61 2 4370 9500

Fax: +61 2 4372 1430

Email: info@rescan.com.au



Above is shown a magnetic splice signature for one splice in February and in March.

A change to an area in the leading left of the splice was noted during the March scan.

Onsite inspections revealed that two cords had looped out of the splice and had broken whilst a third cord was damaged. Repairs were able to be quickly made to prevent any further damage.